



# SPECIAL PRESENTATION AND TECHNICAL TOUR



## BakerRisk's Wilfred E. Baker Test Facility: State-of-the-Art Industrial Hazards Testing

**Presentation: Tuesday, July 16**



**Technical Tour: Friday, July 19**

### SPECIAL PRESENTATION

**Tuesday, July 16, 2019, 8:15 am - 10:00 am**  
**Refer to Conference Program for Location**

Baker Engineering and Risk Consultants, Inc. (BakerRisk®) invites attendees of the ASME Pressure Vessels and Piping (PVP) Conference to join a Special Presentation and participate in a technical site tour to learn about BakerRisk's state-of-the-art Wilfred E. Baker (WEB) Test Facility.

BakerRisk developed the WEB test facility to provide the most advanced technologies for conducting experimental testing and R&D of various industrial hazards.

A Special Presentation during the PVP Conference on July 16th will introduce attendees to the BakerRisk WEB Test Facility and our testing capabilities. This session is open to all ASME PVP Conference attendees.

A technical tour of the facility will be hosted by BakerRisk on July 19th for 50 guests.

### ABOUT BAKERRISK

BakerRisk provides engineering consulting services to a variety of organizations in the energy and manufacturing industries, providing solutions for managing industrial hazards such as explosions, high-pressure failures, fires, and toxic releases.

### REGISTRATION

Refer to the ASME PVP website to register for the tour in advance. Otherwise, registration may be available at BakerRisk's exhibit booth during the Conference if there are any remaining tickets.

The Special Presentation and the Technical Tour (including transportation) will be provided. Space for the tour is limited, and attendees must sign a non-disclosure agreement and abide by the site safety rules. Refreshments will be provided.

### TECHNICAL TOUR

**Friday, July 19, 2019, Morning**  
**BakerRisk WEB Test Facility, La Vernia, Texas**

#### Schedule:

- 8:30 am Meet in the lobby of the Hyatt Regency San Antonio Riverwalk Hotel
- 8:45 - 9:30 Chartered bus ride to the test facility
- 9:30 - 10:15 Introduction presentation
- 10:15 - 10:45 Shock tube test demonstration
- 10:45 - 11:15 Bursting pressure vessel test demonstration
- 11:15 - 12:00 Flange leak and jet fire test demonstration
- 12:00 - 12:30 Closing discussion
- 12:30 - 1:15 Chartered bus ride back to hotel

- Attendees are required to bring and present a government issued ID or passport in order to access the test facility (name and ID will be recorded). Attendees are also required to sign a non-disclosure agreement.
- The safety of all attendees is our foremost concern. It is prohibited to enter the facilities while under the influence of alcohol or drugs. Weapons (including knives) are not allowed on site. Alcohol or other drug substances are prohibited on site.
- Tour participants must wear appropriate footwear, including solid shoes (no open toed shoes or high heels) and long pants or jeans (no shorts).
- All forms of photography are prohibited. Cameras or similar devices are not allowed on site. Cell phones must be switched off while on site.
- Space is limited and offered on a first-come, first-serve basis.