Advanced Manufacturing and Repair for Gas Turbines Symposium					
	Ma	rch 19-20, 2019   Siemens Conference Center   Berlin,	Germany		
		Schedule At A Glance			
Tuesday			Reception Ar		
19 March 2019	8:00 - 9:00	Registration and Badge Pick-up	<b>Ground Floo</b>		

Schedule At A Glance				
Tuesday			Reception Area,	
19 March 2019	8:00 - 9:00	Registration and Badge Pick-up	Ground Floor	
	8:00 - 9:00	Morning Coffee	Werner von Siemens foyer, 2nd Floor	
	8:00 - 17:00	Information Desk	Werner von Siemens foyer, 2nd Floor	
	9:00 - 9:15	Welcome and Opening Remarks	Werner von Siemens Hall, 2nd Floor	
	9:15 - 10:30	Tutorial "Designing for Metal Additive Manufacturing" Part 1	Werner von Siemens Hall, 2nd Floor	
	10:30-10:45	Coffee Break	Werner von Siemens foyer, 2nd Floor	
	10:45 - 12:00	Tutorial "Designing for Metal Additive Manufacturing" Part 2	Werner von Siemens Hall, 2nd Floor	
	12:00 - 13:30	Lunch	Mosaic Hall, Ground Floor	
	13:30 - 14:45	Tutorial "Additive Manufacturing and Advanced Repair for Gas Turbine Components" Part 1	Werner von Siemens Hall, 2nd Floor	
	14:45 - 15:00	Coffee Break	Werner von Siemens foyer, 2nd Floor	
		Tutorial "Additive Manufacturing and Advanced Repair for		
	15:00 - 16:15	Gas Turbine Components" Part 2	Werner von Siemens Hall, 2nd Floor	
	16:30 - 16:45	Technical Tours	Meet in Mosaic Hall to be guided to tours	
			Depart conference center for technical	
	16:45 - 18:45	Technical Tours	tours	
10/ 1	19:00 - 20:30	Networking Reception	Mosaic Hall, Ground Floor	
Wednesday 20 March 2019	7:45 - 8:30	Registration and Badge Pick-up	Reception Area, Ground Floor	
	7:45 - 8:30	Morning Coffee	Mosaic Hall, Ground Floor	
	7:45 - 17:00	Information Desk	Werner von Siemens foyer, 2nd Floor	
	8:30 - 8:45	Welcome and Keynote Introductions	Mosaic Hall, Ground Floor	
	8:45 - 9:15	Keynote Presentation	Mosaic Hall, Ground Floor	
	9:15 - 9:25	Technical Break to go to Session Rooms		
	9:25 - 10:55	Session 1-1 Designing for Advanced Manufacturing	Werner von Siemens Hall A, 2nd Floor	
		Session 2-1 Case Studies of Advanced Repair Approaches	Werner von Siemens Hall B, 2nd Floor	
	10:55 - 11:10	Coffee Break	Werner von Siemens foyer, 2nd Floor	
	11:10-12:45	Session 1-2 Materials and Processes for Advanced Manufacturing	Werner von Siemens Hall A, 2nd Floor	
		Session 2-2 Advanced Repair Strategies for Hot Section Turbine Parts	Werner von Siemens Hall B, 2nd Floor	
	12:45-13:55	Lunch	Mosaic Hall, Ground Floor	
		Session 1-3		
	13:55-15:25	Progress in Advanced Manufacturing by GT OEMs - I	Werner von Siemens Hall A, 2nd Floor	
		Session 2-3 Progress in Advanced Repairs by GT OEM's	Werner von Siemens Hall B, 2nd Floor	
	15:25-15:45	Coffee Break	Werner von Siemens foyer, 2nd Floor	
	15:45-17:00	Session 1-4 Progress in Advanced Manufacturing by GT OEMs - II	Werner von Siemens Hall A, 2nd Floor	
		Session 2-4 Materials and Processing for Advanced Repairs	Werner von Siemens Hall B, 2nd Floor	